
CE BAUMGARTNER, ET AL RD-27,719-6 DAVID C. GOLDMAN (518) 387-5927



- line 2 line 1 line 3
- ♦ Parylene on Csl and in photodiode panel epoxy bond area
- □ No Parylene
- △ Parylene on Csl but not in photodiode panel epoxy bond area

Fig. 1






Fig. 2

fraction of epoxy seal containing parylene


CE BAUMGARTNER, ET AL RD-27,719-6 DAVID C. GOLDMAN (518) 387-5927


2/11







4/11


















10/11



11/11

